Work Order ID 75578 October-25-11 3:12:07 PM			*75578*					Nough			Page 1	
Revision ID:	D3325-041 Basket Lid Assembly			Accept	*N900	040	100	* s	etup	Start Stop	*N:	S1* S2*
Start Date: Required Date: Reference:	25/10/2011 Start Qt 08/11/2011 Req'd Q		*1* *1*		Cust Item I Customer:	D:					14.	. 17
Approvals:	Process Plan:M.C	.5	Date: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Tooling: SPC (Y/N):	-	ate:		R		Start Stop		R1* R2*
Sequence ID/ Work Center II				Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr											
D3325	Rev B										***	
*100 *100* Large Fab	Large Fab.	Memo		0.00		÷	_	D	1	<u> </u>	p3	
Large Fab		QtyPart Nu 2D3325-1E 3D3325-3Ii 2D3325-5F	mber Description EndTube 1109 Interior Tube 4109 Italia Lengh Tube Tts appropriately	Batch U27 V27 V944/								
		2-Remove a	all markings from materia	al								
			Weld as per Dwg D3325 eel Rod									
		4-Deburr as	required									

W/O:				WORK ORDER CHANGES									
DATE	STEP		PR	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
	:												
*-													
Part No	:		PAR #:	Fault Category:	NCR:	Yes	No DQA	۱:	_ Date: _				
	F	Resolution:		Disposition:	QA: N	vc c	losed:		Date: _				

NCR:		.,						
		Description of NC		Corrective Action Section B		Verification	A	A
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date		Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
				•	√.			
				·				

Work Orde October-25-11 3		578		*755	578*							Page 2
Revision ID:	D3325-041 Basket Lid As	sembly		Accept	*N900	040	100)*	Setup	Start Stop	*NS	S1*
Start Date: Required Date: Reference:	25/10/2011 08/11/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item II Customer:	D:					IUL	
Approvals:	Process Pla	n:	Date:	Tooling:	Da	ite:	_		Run	Start	*NF	R1 *
			Date:	SPC (Y/N):	Da	ite:				Stop	*NF	₹2*
Sequence ID/ Work Center ID 110 *110* QC Quality Control		Operation Description QC9- Inspect visual per of Memo	QSI004- Fusion Welds	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accep Qty	t Rej Qty	y]	Reject Number	Insp. Stamp
*120 *120* QC Quality Control		QC5- Inspect part compl	eteness to step on W/O	0.00				M	/ 	·/	11 -	04 ()
121 *121* HandFinish		Pressure Wash per QSI00	05 4.3	0.00			/	X.	S A	M.	L11/	 //nU

Hand Finishing

W/O:			V	ORK ORDER CHANG	FS									
DATE	STEP	PRO	CEDURE CH		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Ye	s No DQ	A:	_ Date: _	·					
	Re	esolution:	Disposit	on:	_ QA: N/C	Closed:		Date: _	<u>.</u>					
NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)											
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval					
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da		ion C	Chief Eng	QC Inspector					
16														

Work Order ID 75578 October-25-11 3:12:07 PM					Page 3					
Revision ID: Item Name:	D3325-041 Basket Lid As	•		Accept	*N90004	010 0)* s	etup Star Stop	14.7	11* 22*
Start Date: Required Date: Reference:	25/10/2011 08/11/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:					
Approvals:	Process Pla	an:	Date:	Tooling:	Date:		R	lun Star	"INH	?1*
	QC:		Date:	SPC (Y/N):	Date:			Stop	° *NF	?2*
Sequence ID/ Work Center II 130 *120* Powdercoat Powder Coating	, 439	FINISH TIM **** 2ND COAT START TIM	IE:	Set Up/ Run Hours m 0.00 6 0.00 400 5 f necessary***********************************	Tool ID Too	l# Plan Code	Accept Qty	Reject Qty		Insp. Stamp
140 *140* QC Quality Control		QC3- Inspect Part Finish Memo		0.00				/ /}_		of O

W/O:		(2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	W	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQA:	Date: _	
	R	esolution:	Disposition	on:	_ QA: N/C Clo	sed:	Date: _	
NCR:		1	WORK ORE	ER NON-CONFORM	ANCE (NCR			
		Description of NC	Description of NC Corrective Action Section B					Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	QC Inspector
in								
l								1

Work Order ID 75578 October-25-11 3:12:07 PM				*75578*								Page 4
Item ID: Revision ID: Item Name:	D3325-041 Basket Lid Ass	embly		Accept	*N900	040	100)* s	Setup	Start Stop	*N:	S1* S2*
Start Date: Required Date: Reference:	25/10/2011 08/11/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	D:					14.	
Approvals:	Process Plan	n:	Date:	Tooling: SPC (Y/N):		ate:		F	Run	Start Stop		R1* R2*
Sequence ID/ Work Center II 150 *150* Packaging Packaging)	Operation Description Identify as per dwg & S Memo	tock Location: 6-A W/0 455-70	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
*160 *160* QC Quality Control		QC21- Final Inspection Memo	- Work Order Release	0.00						11/	11/7	
											ه (لالا	(V,)

\$ (1/11/0)

	. Copaco									
W/O:			WORK ORDER C							
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Y	es N	o DQ	A:	Date:	
		esolution:								
NCR:			ER NON-CONFORM	ANCE (N	CR)					
DATE	STEP	Description of NC			tion B	gn &	Verific		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		ate	Secti	on C	Chief Eng	QC Inspector
							:			

Picklist Print

October-25-11 3:12:12 PM

Work Order ID: 75578

75578

Parent Item: D
Parent Item Name:

D3325-041

Basket Lid Assembly

D3325-041

Start Date: 25/10/2011

Required Date: 08/11/2011

Page 1

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:A05.02.09New issueKJ/JLM

IPP Rev:B 08-12-16 attach DEO DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Stat
D3328-1 *D3328-1* Basket Hinge		Manufactured	No			100	Each	23.0000	**	2 \mathcal{M}	11/10	726
				Location WA005	33871	Loc	Oty 23 23	Loc Code	-1	ରି ।	-	
D3349-1 *D3349-1* Spacer Bushing		Manufactured	No		33071	100	Each	28.0000	2 **		W 11	10/26
				Location WA005	44401	Loc	Oty 28 28	Loc Code	7	Q _v)	-	•
D3352-I *D3352-1* Label Plate		Manufactured	No			100	Each	14.0000	1 **	-d	H 11	10/26
				Location WA005	<u>1</u> 41925	<u>Loc</u>	Oty 14 14	Loc Code	_	(IV)	-	
D3367-1 *D3367-1* Mounting Bracket		Manufactured	No			100	Each	20.0000	2 **	<u>2</u>	J 11	10/26
				Location WA005	43228	<u>Loc</u>	Oty 20 20	Loc Code	_	(2x)	_	

	•	·								
W/O:			WORK ORDER CHAN							
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							······································		i	
Part No	·	PAR #:	Fault Cate	gory:	NCF	R: Yes N	lo DQ	A :	Date: _	· · · · · · · · · · · · · · · · · · ·
	R	esolution:	Dispositio	n:	QA:	N/C Clo	sed:		Date: _	
NCR:			WORK ORDER NON-CONFOR							
DATE	STEP	Description of NC Section A	Initial	Action Description	tion B	Sign &	Verific Secti		Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date				
								٠		
	1		1				I		[·	

Picklist Print

October-25-11 3:12:12 PM

Page 2

Work Order ID: 75578

Parent Item:

D3325-041

Parent Item Name: Basket Lid Assembly

75578

D3325-041

Start Date: 25/10/2011

Required Date: 08/11/2011

Start Qty: 1.00

Required Qty: 1.00

M4130NTS0.500W.035

Purchased

No

100

270.9988

f

20.5416

**

21.62274

119441

M4130NTS0 500W 035

4130 Square tube .500 x .500 x .035w


Location Loc Qty MAT034 270.9988 109127 216 109385 15.75 112786 39.2488

Loc Code

7.21

Dart Aerospac	e Ltd
---------------	-------


N/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	CEDURE CHAI	· <u> </u>	·	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		•	•									
			·									
								-				
					٠.							
				,					,			
Part No:		PAR #:	Fault Categ	gory:	NCF	R: Yes N	lo DQA	· .	Date:			
Resolution:		Disposition	n:	QA:	N/C Clo	sed:		Date: _				
NCR:		. V	VORK ORDE	R NON-CONFORM	IANCE	(NCR)						
DATE	CTED	Description of NC			ction B		Verific	ation	Approval	Approval		
DAIE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector		
									i			
					*							
·												
					. :							
					•				·			




W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No:		PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQ	A:	Date:				
Resolution:			_ Disposit	ion:	QA: N/C	Closed:		Date: _				
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NC	R)						
DATE	STEP	Description of NC Section A	Corrective Action Section		Sign	& Secti	Verification Approval Section C Chief Eng		Approval QC inspector			
			Chief Eng	Chief Eng	Dat	е						
					,							
			:									




ſ	DESIGN PH	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAN	
Ī	CHECKED,	APPROVED:	DRAWING NO. D3325	REV. B
-	DATE	<u> </u>	TITLE	SHEET 2 OF 3
Ŀ	05.04.25		BASKET LID ASSEMBLY	1:4



VIEW A-A








Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CH	JRE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									·		
			77.77								
			•					!			
						,					
		PAR #:									
Resolution:									Date:		
NCR:			WORK ORI	DER NON-CONFOR	MANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section Initial Action Description			Verification			Approval	Approval	
DATE STEP Description						Section C					
		Section A	Chief Eng	Action Descriptio	on	Sign & Date	Sect	ion C	Chief Eng	QC Inspector	
		Section A		Chief Eng	on		Sect	ion C		QC Inspector	
		Section A		Chief Eng	on		Sect	ion C		QC Inspector	
		Section A		Chief Eng	on		Sect	ion C		QC Inspector	
		Section A		Chief Eng			Sect	ion C		QC Inspector	
		Section A		Chief Eng	·		Sect	ion C		QC Inspector	
		Section A		Chief Eng	·		Sect	ion C		QC Inspector	
		Section A		Chief Eng	·		Sect	ion C		QC Inspector	
		Section A		Chief Eng	· .		Sect	ion C		QC Inspector	
		Section A		Chief Eng	·		Sect	ion C		QC Inspector	



DESIGN PH	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO,	
CHECKED	APPROVED	DRAWING NO.	REV. B
All T	─ ₩→	D3325	SHEET 3 OF 3
DATE		TITLE	SCALE
05.04.25		BASKET LID ASSEMBLY	1:4



THE SOCIAL DARK APPACEACE LT

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

(SCALE 1:2)

atsst

W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
								1 Tod Mgi				
Part No:		PAR #:	Fault Categ	jory:	_ NCR: Yes	No DQA	۱:	Date: _				
Resolution:												
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)						
DATE	OTED	Description of NC			Section B Verifi			Approval	Approval			
DATE	SIEF	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector			
		· · · · · · · · · · · · · · · · · · ·										

75578

DRAWING	NO.	TITLE		REV. B	DART AE	ROSPACE L	TD	D.E.O. NO.		SHEET NO.	SCALE
D3325		BASKET LI	D ASSEMBLY		ENGINEE	RING ORDE	R	D3325-B-1		SHEET 1 OF 1	NTS
DRAWN	AJS		CHECKED	_#	MFG. APPR.	\overline{R}	AP	PROVED	NP	DE APPR.	
DATE	08.11.	28	DATE	08.11.28	DATE	08.12.01	DA	TE	08.12.01	DATE 08.12.01	

1) SHEET 1 MODIFY PARTS LIST AS SHOWN:

PART LIST FOR D3325-041 BASKET LID ASSEMBLY

Part No.	Quantity	Description
	1/	

IS:

	1	
MS20600AD4W5	32	RIVET

WAS:

		Т -	
MS20600AD4W3	32	RIVET	

2) UPDATE SHEET 3 DETAIL B ACCORDINGLY.

COPYRIGHT © 2008 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED POR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart	Aeros	pace	Ltd
------	--------------	------	-----

Dail	. oopao	o Eta										
W/O:			WORK ORDER CHANGES									
DATE	STEP		OCEDURE CHAN	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								_				
								<u> </u>				
Part No):	PAR #:	Fault Categ	jory:	NC	R: Yes	No DQ	A:	Date: _			
	F	Resolution:	Disposition	1:	QA	N/C CI	osed:		Date: _			
NCR:			WORK ORDE	ER NON-CONFO	RMANCE	(NCR)					
DATE	STEP	Description of NC			Section B			cation	Approval	Approval		
DATE	SIEP	Section A	Initial Chief Eng	Action Descrip	otion 				Chief Eng	QC Inspector		
					·							
					····							
							-			·		
1	1		1			1			\	1		